

Application program 920504 (FW V05)

Improvements:

- Problem with the triggering of movement when the default parameterization is loaded was solved

Application program 920503 (FW V05)

Improvements:

- PL-Link problem was solved

Application program 920503 (FW V04)

Improvements:

- The sensibility can be now adjusted

Application program 920502 (FW V03)

Improvements:

- Locking function included (as the UP258E22)
- Detection was improved

Application program 920501 (FW V02)

Improvements:

- The sensibility was improved