

QMX6 Room Sensors/Units	S55720-S604 to S55720-S609
QMX6.P30/40/70/34/44/74	S55720-S642 to S55720-S647
QMX6.P30/40/70/34/44/74-1BSC	

Overview

Firmware version on GAMMA-TD	Firmware version on device	ETS Application program
V02	V2.05	920x11 V1.1
V01	V1.41	920x10 V1.0

FW V02 (V2.05)

FW update information:

- For QMX6.P70/74/70-1BSC/74-1BSC: FW update essential to include necessary Improvement 1 below.
- For QMX6.P30/40/34/44/P30-1BSC/40-1BSC/34-1BSC/44-1BSC: FW update only required to include Improvements 2 and 3 below. Otherwise, do not update FW!

Improvements:

- A major error (MI-441) in the CO2 sensor calibration - that affected CO2 readings after 7.5 days - was fixed (affects QMX6.P70/74/P70-1BSC/74-1BSC)
- An error in the compatibility with the Synco system was fixed by adding Universal Zones in LTE-Mode. (affects all models)
- The ETS database entry was adapted. The parameter setting, for configuring the minimum and maximum configurable fan speed on the display, was adapted. (affects all models)

FW V01 (V1.41)

First release