

FW V04

Improvements:

- The Master-Slave constant lighting control was improved

Application program 920702

Improvements:

- In some situations, there was an ETS error that prevented the configuration of the application

